







Ösenform nach ...	Anzahl der Windungen nach dem Komma	Ösenöffnung versetzt um
 ... Bild 3	...,00 (0)	 0°
 ... Bild 3	...,25 (1/4)	 90°
 ... Bild 3	...,50 (1/2)	 180°
 ... Bild 3	...,75 (3/4)	 270°



 ... Bild 3	...,50 (1/2)	 180°
 ... Bild 3	...,75 (3/4)	 270°



 ... Bild 5	...,50 (1/2)	 0°
 ... Bild 5	...,75 (3/4)	 90°



 ... Bild 5	...,00 (0)	 180°
 ... Bild 5	...,25 (1/4)	 270°